

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O. C. C.
NEW MEXICO OIL CONSERVATION COMMISSION

DEC 1 11 48 AM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
K-3626

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name
2. Name of Operator Reading & Bates Offshore Drilling Company	8. Farm or Lease Name Great Western-State
3. Address of Operator 201 Black Bldg., 825 Maple Ave., Odessa, Texas 79760	9. Well No. 1
4. Location of Well UNIT LETTER F , 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 8-S RANGE 32-E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4401.9 GR	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged November 20, 1966 with verbal approval from New Mexico Conservation Commission, Mr. J. W. Runyan on November 19, 1966.

Plug set by Halliburton:

0 - 30'	- 10 sax	Top of Surface Pipe
310 - 380'	- 25 sax	Base of Surface Pipe
1550 - 1620'	- 25 sax	Top of Anhydrite
2130 - 2192'	- 25 sax	Top of Yates
3330 - 3410'	- 25 sax	Top of San Andres
4050 - 4130'	- 25 sax	across San Andres Porosity

Location marked w/4" pipe giving name, lease & location welded thereon.

Letter will follow when location ready for inspection, etc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>[Signature]</i></u>	TITLE <u>Petroleum Engineer</u>	DATE <u>11-22-66</u>
APPROVED BY <u><i>[Signature]</i></u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		