

Form approved,
May 1969

SUBMIT IN TRIPLICATE
WITH INSTRUCTIONS
(See side)

Form approved,
Budget Bureau No. 42 R1424.

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND SURVEY

SUMMARY NOTICES AND REPORTS ON WELLS

(To be used for notice of completion of well or to report on a different reservoir.
See application for instructions for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM-0403706

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

98KO "B" Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

CATO Sam Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

1-8-30 NMPM

12. COUNTY OR PARISH

CHAUES

13. STATE

NM

1. WELL

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR

BOX 63, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FSL x 660' FWL . Sec 1 (Unit M, SW/4 SW/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4190' R.D.B.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Well completed as a temp. abn. Dry Hole on 12-13-66.
No further use of hole anticipated. Propose to
Plug & Abandon as follows:

SPOT Plugs:

5x
15
Cut + Pull 4 1/2" from approx 1500.
25
30
10

INTERVALS

(PBD) 3550 - 3330'

in + out of 4 1/2" stub

400 - 500 (8 7/8" CSA 457)

Surface & erect P.O.A. marker.

Make final cleanup and restore ground to contour.

RECEIVED

AUG 20 1969

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

TD 3662'
PBD-3550'
8 7/8" CSA 457' - circ
4 1/2" CSA 3662' 800 SX
Perfs: 3463-3536'

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Orea Freeman

DATE AUG 19 1969

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL ANY:

TITLE

DATE

0+4-3550-AR
1-N30
1-3000
1-R24

AUG 20 1969

R. L. BECKMAN

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side