

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

HOBBS OFFICE O. C. C.
NEW MEXICO OIL CONSERVATION COMMISSION
Dec 1 11 40 AM '66

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>	
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name Howell	
9. Well No. 1	
10. Field and Pool, or Wildcat Wildcat	
12. County Chaves	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - Wildcat
2. Name of Operator Atlantic Richfield Company
3. Address of Operator P. O. Box 1978, Roswell, New Mexico
4. Location of Well UNIT LETTER D , 460 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 34 TOWNSHIP 6-S RANGE 31-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4434' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was drilled to a T.D. of 4100' in the San Andres. Drill stem tests and electric logs indicated no commercial hydrocarbons. We propose to plug & abandon by setting the following Incor cement plugs. 10.6#/gal SGOE mud will be used to spot these plugs.

25 sx from 3780-3880'	25 sx from 550-650'
25 sx from 1900-2000'	25 sx from 325-425'
25 sx from 1500-1600'	

10 sx will be put in top of well. 8-5/8" csg set @ 373.97' will remain intact. A dry hole marker will be installed and location cleared and levelled.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **O. D. Bretches** TITLE **Dist. Drilling Supervisor** DATE **11-30-66**

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: