

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O.C.C.  
NEW MEXICO OIL CONSERVATION COMMISSION  
Dec 9 11 51 AM '66

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Union Texas Petroleum Corporation	8. Farm or Lease Name Baskett
3. Address of Operator 1300 Wilco Bldg., Midland, Texas	9. Well No. 4
4. Location of Well UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>11</u> TOWNSHIP <u>8-S</u> RANGE <u>30-E</u> NMPM.	10. Field and Pool, or Wildcat Cato (San Andres)
15. Elevation (Show whether DF, RT, GR, etc.) 4134' GL (est)	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 11.03.

11-19-66 TD 516'. Set 8-5/8" 28# used casing at 511' w/300 sx. cement. WOC 24 hours. Tested casing to 1000# for 30 mins. Tested OK. Cement circulated.

11-25-66 TD 3600'. Set 4 1/2" 9.5# new casing at 3596' and cemented w/500 sx. Ran T.S. and found top of cement outside of 4 1/2" casing at 2141'. WOC 24 hours. Tested casing to 1000# for 30 minutes. Tested OK.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Chas. B. Spain TITLE Office Supervisor DATE 12-8-66

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: