

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION C.

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

APR 21 11 43 AM '67

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Champlin Petroleum Company		5. State Oil & Gas Lease No. OG - 419
3. Address of Operator P. O. Box 872, Midland, Texas		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>8-S</u> RANGE <u>32-E</u> NMPM.		8. Farm or Lease Name Signal "A" State
		9. Well No. 1
		10. Field and Pool, or Wildcat Chaveroo - San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4469 DF		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Started plugging well April 16, 1967. Loaded hole with 9.5# mud. Set 25 sack cement plug from 3840' to 4163'. Shot off 4 1/2" OD casing at 1490', left 2942' of 4 1/2" OD casing in well. Pipe left in hole covered the salt section. Set 25 sack cement plug from 1619' to 1440', 25 sack cement plug from 411' to 329' (in and out of surface pipe). 8 5/8" OD surface pipe set at 375' left in well. 10 sack cement plug set in top of surface pipe. Installed dry hole marker. Completed plugging well 3:00 P.M. April 18, 1967.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Walter B. Randolph TITLE District Clerk DATE April 20, 1967

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: