

HOBBS OFFICE O. C. C.

JAN 9 7 43 AM '67

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Union Texas Petroleum		8. Farm or Lease Name Crosby
3. Address of Operator 1300 Wilco Bldg., Midland, Texas		9. Well No. 3
4. Location of Well UNIT LETTER <u>D</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>15</u> TOWNSHIP <u>8-S</u> RANGE <u>30-E</u> NMPM.		10. Field and Pool, or Wildcat Cato (San Andres)
15. Elevation (Show whether DF, RT, GR, etc.) 4103' GL		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 1:30 PM 12-16-66

12-16-66 TD 522, set 8-5/8" 28# used casing at 517' and cmted. w/300 sx.
Cmt. circulated. WOC 24 hrs. Tested 8-5/8" casing to 1000#.
Tested OK.

12-26-66 TD 3541', set 4 1/2" OD 9.5# new casing at 3536' and cmted. w/500 sx.
Top of cmt. outside of 4 1/2" OD casing at 2400' by T.S. WOC 24 hrs.
Tested 4 1/2" casing to 1500# for 30 minutes. Tested OK.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Office Supervisor DATE 1-6-67

APPROVED BY _____ TITLE _____ DATE _____