STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUT	OH	Γ	
BANTA PE		Γ	
FILE			
V.8.0.4.			
LAND OFFICE			
TRANSPORTER	OIL		
	GAS		
OPERATOR		<u> </u>	
PROBATION OFF	HCE		

OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501

Form C-104 Revised 10-01-78 Format 06-01-83 Page 1

REQUEST FOR ALLOWABLE AND AUTHORIZATION TO TRANSPORT OIL AND NATURAL GAS

Operator						
KELT OIL & GAS, INC.		· · · · · · · · · · · · · · · · · · ·				
Address .						
P.O. Box 1493, Roswell, New Mexico 88201						
Reeson(s) for filing (Check proper box)	Reason(s) for filing (Check proper box) Other (Please explain)					
New Well Change in Transporter of:						
Recompletion Oti C	Recompletion Oti Dry Gas					
Change in Ownership Casinghead Gas	Condensate February 2, 1988					
If change of ownership give name A pollo Energy, Inc., P.	0. Box 8097, Ros	well, New Mexico 88201				
II. DESCRIPTION OF WELL AND LEASE						
Lesse Name Well No. Pool Name, Including I	ormation	Kind of Lease Loase				
New Mexico "H" State , 16 Cato San	Andres	State, Federal or Fee State	K3259			
Location						
Unit Letter M : 660 Feet From The South Li	ne and 660	Feet From TheWest				
Unit Letter						
Line of Section 16 Township 8S Range	30Е , ммр м	. Chaves	County			
III. DESIGNATION OF TRANSPORTER OF OIL AND NATURA	L GAS					
Name of Authorized Transporter of Oli 🚺 or Condensate	Address (Give address to which approved copy of this form is to be sent)					
Navajo Ref.	P.O. Box 159, Artesia, New Mexico 88210					
Name of Authorized Transporter of Casinghead Gas 🔯 or Dry Gas 🗌						
Cities Service Oil & Gas Corp. P.O. Box 300, Tulsa, Oklahoma 74102						
Unit Sec. Twp. Rge.	Is gas actually connect					
If well produces oil or liquids, give location of tanks. F 16 8S 30E	Yes	8/1/68				

11

If this production is commingled with that from any other lease or pool, give commingling order number:

NOTE: Complete Parts IV and V on reverse side if necessary.

VI. CERTIFICATE OF COMPLIANCE

I hereby certify that the rules and regulations of the Oil Conservation Division have been complied with and that the information given is true and complete to the best of my knowledge and belief.

•	H	1
	(Signature)	/
Christian D	eleris - President	·
	(Title)	
Jar	nuary 29, 1988	
	(Date)	

OIL CONSERVATION DIVISION				
BY	······			
ORIGINAL SIGNED BY JEERY SEXTON				

DISTRICT I SUPHAVISOR This form is to be filed in compliance with RULE 1104.

If this is a request for silowable for a newly drilled or deepened well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

All sections of this form must be filled out completely for allowable on new and recompleted wells.

Fill out only Sections I. II. III, and VI for changes of owner, well name or number, or transporter, or other such change of condition.

Separate Forms C-104 must be filed for each pool in multiply completed wells.

IV. COMPLETION DATA

Designate Type of Completi		OII Well	i Gas Well I I	New Well	i Workover I	i Deepen I I	' Piug Back I I	' Same Res'v, 1 1	Diff. Res'v.
Date Spudded	Date Compl	, Ready to P		Total Depth	<u> </u>		P.B.T.D.	<u></u>	±
evations (DF, RKB, RT, GR, etc.) Name of Producing Formation		Top Oil/Gas Pay			Tubing Depth				
Perforations	<u></u>		<u></u>	_ .	<u></u>		Depth Casin	ng Shoe	
		TUBING,	CASING, AN	DCEMENT	NG RECOR	D			
HOLE SIZE CASING & T		NG & TUBI	NG SIZE	DEPTH SET		SACKS CEMENT		٩٣	
			·····						
U TTOT DATA AND DECHEST	TOD ALLO	WADLE (Test must be a		of total value	a of load of	and must be a	aval to as ava	and top allow

V. TEST DATA AND REQUEST FOR ALLOWABLE (Test must be after recovery of total volume of load oil and must be equal to OIL WELL able for this depth or be for full 24 hows)

Date First New Oil Run To Tanks	Date of Test	Producing Method (Flow, pump, gas lift, etc.)		
Longth of Test	Tubing Prossure	Cosing Pressure	Choke Size	
Actual Prod. During Teet	ОЦ-ВЫ.	Water - Bbls.	Gas+MCF	

GAS WELL

Actual Prod. Test-MCF/D	Longth of Test	Bbis. Condensate/MMCF	Gravity of Condensate
Tealing Method (pilol, back pr.)	Tubing Pressure (Shnt-in)	Cosing Pressure (Sbut-im)	Choke Bize

.

.