

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

APR 20 7 15 AM '67

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-3189	
7. Unit Agreement Name	
8. Farm or Lease Name	
Shell "A" State	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Undesignated	
12. County	
Chaves	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator
Champlin Petroleum Company	3. Address of Operator
P. O. Box 872, Midland, Texas	4. Location of Well
UNIT LETTER <u>G</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>8-S</u> RANGE <u>32-E</u> NMPM.	15. Elevation (Show whether DF, RT, GR, etc.)
	4493 DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL BACK CASING	<input checked="" type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input checked="" type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>

REMEDIAL WORK	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

ALTERING CASING	<input type="checkbox"/>
PLUG AND ABANDONMENT	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal consent was received from Mr. Joe D. Ramey on April 17, 1967 to plug and abandon as follows:

- (1) 25 sacks over perforations (4298-4346)
- (2) 25 sacks at top of 4 1/2" with all or part of plug in open hole
- (3) 25 sacks at top of salt section
- (4) 25 sacks at bottom of surface pipe (part in and out of pipe)
- (5) 10 sacks in top of surface
- (6) Mud between plugs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Walter R. Ramey

TITLE District Clerk

DATE April 18, 1967

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY: