

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

K-2019

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Murphy Operating Corporation

3. Address of Operator

P. O. Drawer 2648, Roswell, New Mexico 88202-2648

7. Lease Name or Unit Agreement Name

Haley Chaveroo San Andres
Unit Sec. 3

8. Well No.

9

9. Pool name or Wildcat

Chaveroo San Andres

4. Well Location

Unit Letter I : 1980 Feet From The South Line and 660 Feet From The East Line

Section

3

Township

8 South

Range

33 East

NMFM

Chaves

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☒

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-7-90 TIH with bit, drill collars and tubing. Clean out well from 4349' to
thru 4388' PBTD. TIH with RBP and packer and test casing. Found hole @ 3112'.
12-17-90 TOH. TIH and set CIBP @4200 TOH. TIH with cement retainer and set @ 2625'.
Attempted to establish rate. TOH and checked stinger. TIH with packer and
set @ 2559'. Test to 1000 psig. Held OK. TIH with bit and drill out cement
retainer. TIH with packer and test casing to 900 psig. Held OK. TIH and
drill out CIBP. TIH with tubing, pump and rods. Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Lori Brown

TITLE

Production Supervisor

DATE

3-1-91

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 07 1991