

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

REQUIRE IN TROPICAL
(Other instructions on
reverse side)

Check appropriate box to indicate nature of notice, report, or other data.
1. ☒ Sundry notices and reports on wells
2. ☐ Other

SUNDY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		7. ☐ OTHER
2. NAME OF OPERATOR Union States Petroleum Corporation		8. ☐ PARTIAL PLUG BACK
3. ADDRESS OF OPERATOR 1200 Wilson Building, Indiana, Office 7101		9. ☐ WELL NO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1200' TWT & 600' TWT		10. ☐ PARTIAL PLUG BACK
14. PERMIT NO.	15. ELEVATIONS (Show whether LF, HT, GR, etc.) 4025 GR	11. ☐ SURFACE PLUG BACK
		12. COUNTY OR PARISH
		13. STATE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACURE TREATMENT ☐	REPAIRING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐

(Note: Report results of multiple completion on well completion or its completion report and add notes.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and logs pertinent to this work.)

7/13: Perf 3290-3295'. Isobins w/1500 gals 15% acid.

7/14: See plan @ 3100. Treated pumps 3290-3295' & 3295-3300' w/1500 gals 15% acid and flushed w/1500 gals treated fresh water. Wellhead flushed w/1500 gal. water. Bore hole in 6 1/2" gal. fresh water. Treated the stage w/1500 gals 20% acid & flushed w/1500 gals treated fresh water.

7/15: Run tubing and set at 3000' w/perf tubing job from 3271-3275'. The well down on pump.

18. I hereby certify that the foregoing is true and correct

SIGNED J. W. [Signature] ATTEST [Signature] DATE 9/1/59

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

FOR RECORDED
[Signature]
State Engineer

*See Instructions on Reverse Side