Form 9-331 (May 1963)

1.

UNITED STATES SUBMIT IN TRIPLIC TE (Other instructions represented) DEPARTMEN OF THE INTERIOR (verse side) UNITED STATES

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

Chaves

N.M

	GEOLOGICAL SURVEY	NM 0346362 (b)
SUNDRY NO (Do not use this form for pr Use "APPI	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
OIL GAS WELL OTHE	Plug & Abandon	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Atlantic Richfield	Company	8. FARM OR LEASE NAME Woodman Federal
3. ADDRESS OF OPERATOR P. O. BOX 1710, Hol	obs, New Mexico 88240	9, WELL NO.
4. LOCATION OF WELL (Report location See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT Cato - San Andres	
1980' FNL & 660' F	EL (Unit letter H)	11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA 28-T8S-R30E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE

16.	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data							
	NOTI	CE OF IN	NTENTION TO:		SUB	SEQUI	INT REPORT OF:	
TEST W	ATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF		REPAIRING WELL	
FRACTUE	E TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT		ALTERING CASING	
SHOOT O	R ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING		ABANDONMENT*	

Plug & Abandonment (Other) REPAIR WELL CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

4148' GR

On 5/8/75 rigged up & installed BOP. WIH w/bit & scraper to 3400' OK. POH w/bit & scraper. WIH $w/4\frac{1}{2}$ cmt retr on 2-3/8" tbg, set @ 3400'. Circ hole w/heavy gelled mud. Displaced 95 sx Cl C cont'g 4% gel below retr. MP SI 250#. Spotted 5 sx on top of retr. POH w/tbg. Worked csg & cut 41" OD csg @ 2246' & recovered. WIH w/tbg OE to spot cmt, could not get below 660'. USGS notified. OK to spot plug @ 660'. Spotted 75 sx Cl C, .4% HR-4, @ 660-480'. Tagged top of cmt @ 480' w/tbg. Spotted 75 sk cmt plug across 8-5/8" csg shoe 330-130'. Spotted 10 sk cmt plug @ surface. Erected regulation dry hole marker. Well P&A effective 5/14/75. Location to be cleaned & levelled in accordance w/previously approved USGS & BLM stipulation.

10 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
18. I hereby certify that the foregoing is true and correct SIGNED	TITLE	Dist. Drlg. Supv.	DATE 5/29/75
(This space for Federal or State office use) APPROVED BY, CONDITIONS OF APPROVAL, IF ANY:	TITLE		DATE

*See Instructions on Reverse Side

COT G 1975

COT G 1975

COT G 1975