

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRI
(Other instructive
verse side)

DATE
on re-

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0346362-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill into deep or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FSL x 660' FEL Sec 21 (Unit P, SE 1/4 SE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

4145' R.D.B.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

WOODMAN Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

CATO San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

21-8-30 NMPM

12. COUNTY OR PARISH

CHAVES

13. STATE

N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 2-5-69 Physical abandonment of well was made. Plugged as follows:
Spotted 25' x plug 3483-3100.
Shot 4 1/2" Casing @ 1917' and 1806' - Pulled from 1806'.
25' x Cement plugs spotted @ - In & Out of 4 1/2" casing stub @ 1806', 8 5/8" Casing shoe @ 300'.
10' x Cement plug @ surface w/ P & A marker.
(All intervals filled w/ mud.)

8 7/8" CSA 300' - cmt circ.

4 1/2" CSA 3596' - cut from 1806'.

P & A Comp 2/5/69

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE FEB 25 1969

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

0-4 USGS. ART

1- NSW
1- SUSP
1- W. Spencer
1- RRY

*See Instructions on Reverse Side

RECEIVED
MAR 11 1969
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

MAY 23 1969

R. L. BECKMA