

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE
(Other Instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-048610-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR PAN AMERICAN PETROLEUM CORPORATION	8. FARM OR LEASE NAME GONZALES Federal
3. ADDRESS OF OPERATOR BOX 68, HOEBBS, N. M. 88240	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT SIETE SAN ANTONIOS
14. PERMIT NO. 660' FNL x 660' FWL Sec. 21 (Unit D, NW 1/4 NW 1/4)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 21-8-31 NMPM
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4227' R.D.B.	12. COUNTY OR PARISH CHAVES
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Production has declined below the economic limit to produce. No workover possibilities. Propose to P & A as follows:

1. Spot 25 cu. cement plug across perfs (3276-70)
 Cement & pull 4 1/2" CSg from free point. (Cp. TCMT-1900')
 Spot 25 cu. In & Out of 4 1/2" Stub (Heavy mud laden)
 " 50 cu " " 8 5/8" CSA 298' (fluid between plugs)
 " 10 cu @ surface & erect P & A marker.
 Make final cleanup and restore ground to contour.

TD - 3857'
 PAD - 3310'
 4 1/2" CSA 3857' w/ 250 Sx.
 8 5/8" CSA 298' w/ 350 Sx. Circ.

T-YATES - 1844'

T-SAN AND - 3012'

RECEIVED

MAR 24 1970

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

RECEIVED

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE AREA SUPERINTENDENT

DATE MAR 18 1970

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

OK 1- USGS-ACT
 1- BCS
 1- SUSP
 1- R24

*See Instructions on Reverse Side

APPROVED

R. L. BECKMA
 ACTING SUPERINTENDENT

Q.L. CONSERVATION COMM.
HOBBES, N. M.

MAR 26 1970

(11)