## NEW XICO OIL CONSERVATION COMMISSION WELL LOCATION AND ACREAGE DEDICATION PLAT

All distances must be from the outer boundaries of the Section. Well No. Operator Ray Morris Exploration Company Southern Petroleum State County Unit Letter Chaves 33 East 8 South Actual Footage Location of Well: line and 1980 West line feet from the South feet from the Dedicated Acreage: Ground Level Elev. Producing Formation Acres 40 Chaveroo 4415 G. L. San Andres 1. Outline the acreage dedicated to the subject well by colored pencil or hachure marks on the plat below. 2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty). 3. If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling. etc? If answer is "yes," type of consolidation \_\_\_\_\_ □ No If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.). No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Commission. CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my kg bwledge and belief. Name Ray Morris Exploration Co. Company March 8, 1969 I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or 1980 0 under my supervision, and that the same is true and correct to the best of my knowledge and belief. Date Surveyed MAR 1959 Registered Professional Engineer and/or Land Surve

1000

2000

1980 2310

1320 1650

660

330

1500