

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLI
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.5. LEASE DESIGNATION AND SERIAL NO.
NM 027395

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Pubco Federal9. WELL NO.
210. FIELD AND POOL, OR WILDCAT
Undesignated11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA**Sec. 21, T-8-S, R-31-E**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4224.6 GL12. COUNTY OR PARISH
Chaves13. STATE
N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐**Temporarily suspend operations**

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☒

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 5-4-69 Drilled out cement to 3804'. pf. 2 hole per ft. @ 3741' & 3743'. - pf. 1 hole per ft. @ 3757, 3760, 3766, 3768, 3775, 3791, 3793 & 3795'. Set pkr on tbg. @ 3787'. Treated pfs. 3791-3795 w/500 gals 15% N.E. acid. Swabbed dry.
- 5-5-69 Re-treated pfs. 3791-3795' w/5000 gals 20% N.E. acid. Had communication into upper pfs.
- 5-6-69 Swabbed 15 barrels dead oil and 62 barrels water.
- 5-7-69 Unable to get to well because of heavy rain.
- 5-8-69 Swabbed 11 barrels oil and 102 barrels water.
- 5-9-69 Swabbed trace of oil and 34 barrels water. Very little fluid entering well.
- 5-10-69 Pulled tubing.
- 5-13-69 Squeezed all pfs. w/50 sx reg. cement containing 8# salt plus 50 sx reg. cement containing .6 of 1% CFR-2 per sack. Squeeze pressure 3500 psi.
- 5-14-69 Drilled out cement to 3772'. pf. 2 holes @ 3741 & 3743 and 1 hole @ 3757', 3760, 3766, & 3768. Ran tubing open ended to 3770'.
- 5-16-69 Treated all pfs. w/500 gals mud acid. Swabbed dry. Re-treated w/2,000 gals 15% N.E. acid.
- 5-17-69 Swabbed dry. Re-treated w/5,000 gals 15% N.E. acid. Swabbed dry.
- 5-20-69 Left all equipment in well and temporarily suspended operations.

RECEIVED
JUL 17 1969
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Mgr. of Brigs & Pross

DATE

7-16-69

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

**File 9-531 when
operations re-commence**

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.