

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-2850, K-665

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name --
2. Name of Operator Coquina Oil Corporation	8. Farm or Lease Name State SGW Com.
3. Address of Operator 418 Building of Southwest, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER 0, 1800 FEET FROM THE East LINE AND 660 FEET FROM THE South LINE, SECTION 36 TOWNSHIP 8-S RANGE 32-E NMPM.	10. Field and Pool, or Wildcat Bar U Penn
15. Elevation (Show whether DF, RT, GR, etc.) GL 4405, KB 4418	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-10-71 Pulled 2-3/8" tbgr., cavity, pkr, and laid all down. Set cast iron B.P. at 8900' in 5-1/2 csg. with 30' cmt. on top of B.P. Loaded hole with mud-laden fluid.

7-19-71 Shot 5-1/2 at 5026'-stuck. Shot 5-1/2 at 4623'- stuck. Shot 5 1/2 at 3683'- came free. Spotted 60 sx cmt. on 5 1/2" stub at 3683'. Laid down 5 1/2 casing. Shot 8-5/8" casing at 1015' - came free. Spotted 35 sx Class H cmt. at 1015'. Spotted 25 sx Class H cmt. at 350'. Laid down 8-5/8" casing. Spotted 10 sx in top of 13-3/8" casing. Installed dry hole marker. P & A completed 7-22-71.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J.B. Taylor TITLE Sup't. DATE 7-23-71

APPROVED Nathan E. Olegg TITLE OIL & GAS INSPECTOR DATE JUN 23 1972

CONDITIONS OF APPROVAL, IF ANY: