

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

AUG 22 10 40 AM '69

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>DRY HOLE</u>	7. Unit Agreement Name
2. Name of Operator <u>PAN AMERICAN PETROLEUM CORPORATION</u>	8. Farm or Lease Name <u>CROSBY "J"</u>
3. Address of Operator <u>BOX 68, HOBBS, N. M. 88240</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>D</u> <u>990</u> FEET FROM THE <u>NORTH</u> LINE AND <u>660</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>34</u> TOWNSHIP <u>7-S</u> RANGE <u>30-E</u> NMPM.	10. Field and Pool, or Wildcat <u>WILDCAT</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4100' R.D.B.</u>	12. County <u>CHALES</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Permanent abandonment effected as follows:  
Spotted 35 sq. across perfs: 3550'-3393':  
Shot 8 5/8" CG @ 1886' & pulled from 1824'. Spotted 25 sq  
In & Out of Stub.  
Spotted 25 sq @ 1050' (T-SALT)  
Spotted 25 sq In & Out of 13 3/8" CSA 283'.  
Spotted 10 sq @ Surface & erected P&A marker.  
Final Cleanup shall be made and ground restored  
to contour.

P&A Comp 8-6-69

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  
SIGNED [Signature] TITLE Area Engineer DATE AUG 21 1969

APPROVED BY [Signature] TITLE Geologist DATE APR 22 1970  
CONDITIONS OF APPROVAL, IF ANY:  
1- SUSP  
1- RRY  
2- WFS