

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLI
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-B1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0109856

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

BAM Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 21-T14S-R30E

12. COUNTY OR PARISH 13. STATE

Chaves

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole

2. NAME OF OPERATOR

Jack L. McClellan

3. ADDRESS OF OPERATOR

Box 848, Roswell N.M. 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FS and FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3857' G.L.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐,XXX
XXX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

On 3/20/70, Notice of intention to abandon this well was filed and
Subsequently approved 3-23-70.

On 5/1/70, Notice of a change in plans was filed with intentions of
reclassifying well as a shut in gas well.

6/3/70 This notice of change of plans indicates our intention to
plug and abandon the well as originally approved 3/23/70. Well will
be killed with heavy mud (nitrogen Gas), spot 100' cement plug at T.D.,
place 100' plug in and out of 4 1/2" casing cut-off. If the stub is
above the base of salt, will spot 100' plug at base of salt. Place
100' cement plug at stub of 8 5/8" casing. If near surface will fill
balance of pipe with cement, if not, will spot 10 sack plug at surface,
Set dry hole marker and clean location.

RECEIVED

JUN 5 1970

RECEIVED

JUN - 4 970

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Gene Milford

TITLE

Prod. Supt.

DATE

6-3-70

(This space for Federal or State office use)

TITLE

DATE

APPROVED
JUN - 4 1970
R. L. BECKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

RECEIVED

JUNE 1970

**OIL CONSERVATION COMM.
HOBBS, N. M.**