

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLI
(Other instructions
reverse side)B*
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0343765

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal 28

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Vest Ranch Queen

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 28 T. 14S, R. 30E

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

1.

OIL
WELL ☐GAS
WELL ☐

OTHER

DRY

2. NAME OF OPERATOR

Jack F. Grimm

3. ADDRESS OF OPERATOR

P. O. Box 35 Abilene, Texas 79604

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660 FNL & 1980 FNL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3893.8 GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3/11/71 Commenced drilling

3/19/71 Set 492 - 8 5/8 surface casing cemented with 150 sx to top

3/25/71 Drilling @ 1555'

4/5/71 Total depth 2,400', requested permission to plug and abandon. Granted by Artesia office. Well had 270' salt water fill up in hole overnight with skim of oil. Fluid came from Queen Sand @ 2,158'-2,171'.

Plan to Plug in the following manner:

1. Spot 100'/30 sx Unit plug 2200 - 2100'

2. Spot 100'/30 sx Unit plug 1200 - 1100'

3. ~~Spot~~ 100'/30 sx Unit plug in & eat
8 7/8" Cog 550 - 4504. Place 10' Regulation Marker in 10'/10 sx
Surface plug5. ~~Make~~ ~~between~~ ~~all~~ ~~plugs~~, Clean location & Return to Original condition.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Operator

DATE

April 5, 1971

(This space for Federal or State office use)

TITLE

DATE

APPROVED
MAY 11 1971R. L. BECKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment: data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of putting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE : 1963-O-685229

847-485

RECEIVED
MAY 12 1971
D. C. C.
ARTESIA, OFFICE

RECEIVED

MAY 17 1971

U.S. CONSERVATION COMM.
HODGES, R. M.