NEW MEXICO OIL CONSERVATI	CON COMMISSION
---------------------------	----------------

	Glenn Pet. Comp. ADDRESS 2900 Maple, Dallas							
OPERATOR								
	Cato		LEASE Crosby			WELL NO.		
LOCATION	1480 FEL + 16				30E			
			ON RECORD		· · · · ·			
		DEPTH	DEGREES					
		270	1/4					
		759	1/4					•
		1250	1/2			,		
		1750	3/4					
		2118	2 -1/ 4					
		2692	1-3/4					
		3035	3/4					
	•	3320	1/2			•		
		3472	1					
		3587	3/4					
		3720	3/4	,				

Certification of personal knowledge of Deviation Record:

I hereby certify that I have personal knowledge of the data and facts placed on this form, and that such information is true and complete.



STATE OF TEXAS COUNTY OF MIDLAND

Before me, the undersigned authority, on this day personally appeared $J_*E_*R_*$ Sheeler , known to me to be the person whose name is subscribed hereto, who, after being duly sworn, on oath states that he is acting at the direction and on behalf of the operator of the well identified in this instrument and that such well was not intentionally deviated from the vertical.

Signature <u>Manager -</u> Ard Drilling Company Title

Sworn and Subacribed to before me, this the 20th day of August , 1971

RM 95m

Notary Public in and for Midland County, Texas. S. R. McKINNEY, JR.



X BYRON JACKSON INC.

.

CEMENTING AFFIDAVIT

I, Gene Leeth, being of lawful age and having full knowledge of
the facts herein below set out do state: I am employed by Byron Jackson Inc.
On <u>8-17-71</u> , 19, BYRON JACKSON INC. performed the cementing
operation herein described for <u>Glenn Petroleum</u> on their
Well No on the Grosby lease
located in <u>Chaves</u> County, State of <u>N.M.</u> .
county, state of
CASING CEMENTING: Name or type of string was <u>Oil String</u> . Information
provided by the Customer Company states that the casing was $\frac{1}{100}$ in. O.D.
set in $7-7/8$ inch hole, and that the casing depth set was 3722 feet.
For this job the following materials were used:
125 Sacks - Class C. Cement
125 Sacks - Diamix "M"
An estimated
<u>CEMENT 2LUG</u> : Information provided by the Customer Company states that the
hole size wasinches, and total depth wasfeet. For this job the following materials were used to place plugs as indicated:
Plug fromft. toft. withsacks of
SIGNED: BYRON JACKSON INC.
BY- Gene Teeth Seno - all

DATE: 8-17-71

.