

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N. M. OIL CONS. COMMISSION
P. O. BOX 1980
HOBBS, NM 88241

FORM APPROVED
OMB No. 1004-0135
Expires July 31, 1996

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Am Brit Energy Corp. *Bond & McWilliams Energy Corp Inc*

3a. Address 8080 North Central Expressway Suite 750, LB 77 Dallas TX 75206

3b. Phone No. (include area code) 214-891-8877

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1980' FSL, 1980' FWL
Sec 22, T 13 S, R 30 E

5. Lease Serial No.
NM 17226 A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
Federal 22 #1

9. API Well No.
30-005-20392

10. Field and Pool, or Exploratory Area
Wildcat

11. County or Parish, State
Chaves Co. New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☒ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other _____
	☐ Change Plans	☒ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

- 1. Set CIBP @ 9,700' in 2 7/8" Tbg
- 2. Dump 35' cmt on CIBP
- 3. Shoot 2 7/8" tbg off @ 7,000'
- 4. Shoot 5 1/2" csg off @ 6,900'
- 5. 200' cmt plug from 6,800' to 7,000' (tag plug)
- 6. 130' cmt plug from 4,100' to 4,230'
- 7. 120' cmt plug from 1,967' to 2,087' (tag plug)
- 8. 183' cmt plug from 350' to 533' (tag plug)
- 9. 50' cmt surface plug
- 10. Install dry hole marker
- 11. Clean location
- 12. Seed location

APPROVED
PETER W. CHESTER

AUG 21 1998

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed) Blake C. Wineinger

Signature *[Signature]*

Title Engineer

Date 8-13-98

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by _____ Title _____ Date _____

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office _____

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations or to any member within its jurisdiction.

RECEIVED

AUG 17 '98

**SLM
ROSWELL, NM**

