

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other instructions
verse side)

E*
re

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0298474

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☒ WELL GAS ☐ WELL OTHER ☐

2. NAME OF OPERATOR

3. R. H. Cross
ADDRESS OF OPERATOR

4. E. O. Box 37, Roswell, New Mexico 88201
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' from South & West Lines

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Amerada-Herrell Fed.

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Wildcat
11. SEC. T. R. S. OR BLK. AND
SURVEY OR AREA

Sec. 28, T 13 S-R 30 E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3815 GR

12. COUNTY OR PARISH

13. STATE

Chaves

N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 8-27-72 Set cement plugs from 2258' - 2215' (over Penrose sand) and @ 1965' - 2065' (over Queen sand). Pulled 7" csg. and set open hole bridge plug at 1462'. (Unable to run bridge plug below 1500'). Set cement plug 1462' - 1150' over base of salt @ 1226', & from 650' - 450' over top of salt at 597'.
- 8-28-72 SD Weather.
- 8-29-72 SD Weather.
- 8-30-72 Squeezed 325 sxs. from surface - cement plug from 1462' - 300' - shut off water. 12 sxs. at surface.
- 9-1-72 SD Weather.
- 9-8-72 Installed marker.
- 9-9-72 Will notify when location has been cleaned and is ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE

Operator

DATE

9-9-72

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963 - O-685229

8 47 - 485