

N.M.O.C.D. COPY

Form 9-331
(May 1963)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ MAR 03 1981		5. LEASE DESIGNATION AND SERIAL NO. BLM NM 8255 (22)
2. NAME OF OPERATOR Cockrell Oil Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME (Empty)
3. ADDRESS OF OPERATOR 999 The Main Building, 1212 Main Street, Houston, Texas 77002		7. UNIT AGREEMENT NAME (Empty)
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FEL & 660' FNL Sec. 22, T14S, R30E, Chaves Co., N.M.		8. FARM OR LEASE NAME Occidental - Federal
14. PERMIT NO. (Empty)		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3,891.2' GR		10. FIELD AND POOL, OR WILDCAT Wildcat
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA NE/4 NE/4 Sec. 22, T14S, R30E
		12. COUNTY OR PARISH Chaves
		13. STATE NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:


WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Will plug as follows:
 Perforations @ 10,668' - 10,680'
 Set CIBP @ 10,650' w/50' of Cmt on top.
 Set 150' Cmt Plug @ 7,500'.
 Set 100' Cmt Plug @ 4,500'.
 Cut Casing @ 3,000' and attempt to retrieve.
 Set 150' Cmt Plug @ 3,000' equally across shoe and pipe stub.
 Set 10 sks Cmt @ surface w/well marker - 9# mud to be left in hole.

Plugging operations expected to be completed by 3-31-81.



18. I hereby certify that the foregoing is true and correct

SIGNED Larry R. Tschirhart TITLE Production Engineer DATE 2-23-81

(This space for Federal or State office use)

APPROVED BY (Orig. Sgd.) PETER W. CHESTER TITLE ACTING DISTRICT ENGINEER DATE FEB 27 1981

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963—O-685229

947 - 485

RECEIVED

MAR 9 1981

OIL CONSERVATION DIV