	-∤			Form C-103
TRIBUTION	_			Supersedes Old C-102 and C-103
FE	NEW MEXIC	O OIL CONSERVAT	ION COMMISSION	Effective 1-1-65
	_			<u> </u>
.s.g.s.	_			5a. Indicate Type of Lease
AND OFFICE				State X Fee.
PERATOR				5. State Oil & Gas Lease No.
				LG O444
SUND (DO NOT USE THIS FORM FOR PR USE "APPLICA	RY NOTICES AND RE	PORTS ON WELLS	S DIFFERENT RESERVOIR.	
USE **APPLICA	TION FOR PERMIT - " (FORM (	C-1011 FOR SUCH PROPOS	ALS.)	7. Unit Agreement Name
OIL GAS				7. Gift Agreement Nume
WELL WELL Name of Operator	OTHER- dry hole			8. Farm or Lease Name
Dalport Oil Corp. Address of Operator			<del></del>	Yates-State Con  9. Well No.
	Danis Dida - Nati	a MV deans		•
3471 First National occation of Well	DETER DICK. DETT	AD IN / JOUC		10. Field and Pool, or Wildcat
u n	980 FEET FROM THE	north	660	unders maked
UNIT LETTER	FEET FROM THE	LISE	AND FEET	FROM
THE CAST LINE, SECT	110N TOWNS	128	<b>31</b> E	
THE LINE, SECT	TION TOWNS	5HIPR	ANGE	VMPM.
	15. Elevation	(Show whether DF, R7.	GR. etc.)	12. County
		7.5 gr.		Chaves
Charle	Appropriate Box To		of Notice Report o	
	. Appropriate box 10 INTENTION TO:	indicate Nature	-	JENT REPORT OF:
NOTICE OF	HATERTION 10.		3053EQ(	52, <u>112 51</u>
BEORN BENEDIAL WORK	DUIG AND	ABANDON : REMED	IA: WCSK	ALTERING CASING
REFORM REMEDIAL WORK	PLUG AND			PLUG AND ABANDONMENT
MPORARILY ABANDON			INDI DRELLING OPNS:	LUG AND ABANDONMENT
		571		
LL OR ALTER CASING	CHANGE P		TEST AND CEMENT JOB	
	CHANGE P		TEST AND CEMENT JOB	
OTHER			ER	luding estimated date of starting any propo
Describe Proposed or Completed (work) SEE RULE 1103.  TD 2550 P & A on 6-5-74  30 sx 'H' (100' H H H H 10 sx at surface	Operations (Clearly state al as follows: plug) 2550-2450	. Base salt Base surfac tween plugs. g name and loc	elis pertinent dates, inc  casing  ation.	luding estimated date of starting any propo
Describe Proposed or Completed (work) SEE RULE 1103.  TD 2550 P & A on 6-5-74  30 sx *H* (100* H H H H 10 sx at surface Exected 4* stee Clean and level	operations (Clearly state all as follows:  plug) 2550-2450  1650-1550  175-75  Heavy mud being showing showing led location. Reference of the complete of the	Base salt Base surfactween plugs. g name and loceady for inspe	e casing ation. ction	luding estimated date of starting any propo
Describe Proposed or Completed (work) SEE RULE 1103.  TD 2550 P & A on 6-5-74  30 sx *H* (100* H H H H 10 sx at surface Exected 4* steected 4* steecte	as follows:  plug) 2550-2450  1650-1550  175-75  Heavy mud being showing alocation. Reference of the complete	Base salt Base surfactween plugs. g name and loceady for inspe	e casing ation. ction	6-28-75
Describe Proposed or Completed (work) SEE RULE 1103.  TD 2550 P & A on 6-5-74  30 sx *H* (100* H H H H 10 sx at surface Exected 4* stee Clean and level	operations (Clearly state all as follows:  plug) 2550-2450  1650-1550  175-75  Heavy mud being showing showing led location. Reference of the complete of the	Base salt Base surfactween plugs. g name and loceady for inspe	e casing ation. ction	6-28-75 DATE 1976