Porm 9-331 (May 1963) UNIT STATES SUBMIT IN TRIPLIC! DEPARTMENT of THE INTERIOR (Other instructions of the control of the c	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, use "APPLICATION FOR PERMIT—" for such proposals.)	NM 18508 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS WELL X OTHER 2. NAME OF OPERATOR	7. UNIT AGREEMENT NAME
Phillips Petroleum Company 3. ADDRESS OF OPERATOR	8. FARM OR LEASE NAME
Room 711. Phillips Building. Odessa. Texas 79761 4. Location of Well (Report location clearly and in accordance with any State requirements. At surface (Unit N) 660' FS & 1980' FW lines	Luther - A 9. WELL NO. 1 10. FIELD AND POOL, OR WILDCAT Wildcat
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) Appod 9-5-74 4417 DF	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 18, 85, 32-E 12. COUNTY OR PARISH Chaves New Mexico
Check Appropriate Box To Indicate Nature of Notice, Report, or O NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) Change Plans Check Appropriate Box To Indicate Nature of Notice, Report, or O SUBSEQUE WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) A Atoka Straw	REPAIRING WELL ALTERING CASING

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any nent to this work.)*

1-13-75: WIH w/DP, open ended to 10,000: Cond mud 2 hrs. - Howco spotted 50 sx cement f/ 10,000' to 9850'; 50 sx cement f/ 9500' to 9350'; 50 sx cement f/ 8300' to Displaced casing w/ fresh water, COOH w/DP.

1-14-75: Cleaned mud pits, removed BOP equipt. and test lines Released Warton rig.

Prep to perforate and test San Andres zone

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Title

Title