## N. M. OIL CONS. COMMISSION

P. O. BOX 1980

HOBBS, NEW MEXICO 88240

Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUDGALL OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires March 31, 1993

	LAND MANAGEMENT	5 Lease Designation and Senai No
SUNDRY NOTICES AND REPORTS ON WELLS		NM-0199827-A
Do not use this form for proposals to d	drill or to deepen or reentry to a different reservoir.  OR PERMIT—" for such proposals	6 If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE  1 Type of Well Oth Well Swell Other 2 Name of Operator		7 If Unit or CA, Agreement Designation
		SW 988  8 Well Name and No 15082
6200 Osuna Road, N.E., Albuquerque, New Mexico 87109 (505)884-6084		30-005-20457 10. Field and Pool, or Exploratory Area
Location of Well (Footage, Sec., T., R., M., or Survey	Description)	VEST RANCH QUEEN ASSOC.
610' FSL & 2310' FWL Section 5, T-15S, R-30E, NMPM		11 County or Parish, State 62620
Unit		Chares
CHECK APPROPRIATE BOX	((s) TO INDICATE NATURE OF NOTICE, REPOR	T, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION	
Notice of Intent	Abandonment	Crange of Plans
<del></del>	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
Final Abandonment Notice	Casing Repair	₩ater Shut-Off
	Altering Casing	Conversion to Injection
	L.J Other	Land Dispose Water (Note: Report results of multiple completion on Well Completion of Recompletion Report and Log form)
	all pertinent details, and give pertinent dates, including estimated date of starting tical depths for all markers and zones pertinent to this work. j*	any proposed work. If well is directionally drilled
by Halliburton. Ran tub	-	
. Set 50 Sacks Cement at 206	7' pulled 20 Jts. Tubing. Ran in and Ta	igged Cement at 1707.
. Knocked Off casing at 1268	Pulled Cocing	
3	· Idlied Casing.	
	mped 30 Sacks Cement, 1/2 in Casing Stub	and 1/2 abo <b>gep-0</b> /2"
. Ran Tubing to 1328' and pur Casing Stub. Tagged Cemen	mped 30 Sacks Cement, 1/2 in Casing Stub	k and Targed Cement
Ran Tubing to 1328' and pur Casing Stub. Tagged Cemen  Pulled Tubing to 518' Set at 404'.  Pulled Tubing and Set 50'	mped 30 Sacks Cement, 1/2 in Casing Stub t 1225'.	k and Targed Cement
<ul> <li>Ran Tubing to 1328' and pur Casing Stub. Tagged Cemen</li> <li>Pulled Tubing to 518' Set at 404'.</li> <li>Pulled Tubing and Set 50' 4' Above Surface. Weld We</li> </ul>	mped 30 Sacks Cement, 1/2 in Casing Stubt 1225'.  Cement Plug. Pulled Tubing and Ran Bac  Cement PLUG in 8-5/8" to Surface with 4-  11 Name: Amerada Federal #1, Sec. 5, T-1	k and Targed Cement
<ul> <li>Ran Tubing to 1328' and pur Casing Stub. Tagged Cemen</li> <li>Pulled Tubing to 518' Set at 404'.</li> <li>Pulled Tubing and Set 50' 4' Above Surface. Weld We</li> <li>LOCATION CLEANED UP, LEVEL</li> </ul>	mped 30 Sacks Cement, 1/2 in Casing Stubt 1225'.  Cement Plug. Pulled Tubing and Ran Bac  Cement PLUG in 8-5/8" to Surface with 4-  11 Name: Amerada Federal #1, Sec. 5, T-1  ED, THEN RIPPED.	tk and Targed Cement  1/2" Marker Pipe Set  5S, R-30E. Lse NM 019982
<ul> <li>Ran Tubing to 1328' and pur Casing Stub. Tagged Cemen</li> <li>Pulled Tubing to 518' Set at 404'.</li> <li>Pulled Tubing and Set 50' 4' Above Surface. Weld We</li> <li>LOCATION CLEANED UP, LEVEL</li> </ul>	mped 30 Sacks Cement, 1/2 in Casing Stubt 1225'.  Cement Plug. Pulled Tubing and Ran Bac  Cement PLUG in 8-5/8" to Surface with 4-  11 Name: Amerada Federal #1, Sec. 5, T-1	k and Targed Cement
Ran Tubing to 1328' and pur Casing Stub. Tagged Cemen.  Pulled Tubing to 518' Set at 404'.  Pulled Tubing and Set 50' 4' Above Surface. Weld We.  LOCATION CLEANED UP, LEVEL.  Thereby certify that the foregoing is true and correct Signed W. Hindex.  (This space for Feoeral or State office use)  Appropried as a sport well as a sport of the use.	mped 30 Sacks Cement, 1/2 in Casing Stubt 1225'.  Cement Plug. Pulled Tubing and Ran Bac Cement PLUG in 8-5/8" to Surface with 4-11 Name: Amerada Federal #1, Sec. 5, T-1  ED, THEN RIPPED. PA 3/4/93  OPERATOR	-1/2" Marker Pipe Set -5S, R-30E. Lse NM 019982
Ran Tubing to 1328' and pur Casing Stub. Tagged Cemen.  Pulled Tubing to 518' Set at 404'.  Pulled Tubing and Set 50' 4' Above Surface. Weld We.  LOCATION CLEANED UP, LEVEL.  Thereby certify that the foregoing is true and correct Signed William William State office use.  Approved by Liability under the state of the	mped 30 Sacks Cement, 1/2 in Casing Stubt 1225'.  Cement Plug. Pulled Tubing and Ran Back  Cement PLUG in 8-5/8" to Surface with 4-  11 Name: Amerada Federal #1, Sec. 5, T-1  ED, THEN RIPPED.  OPERATOR  Plugging of The way.	August 29, 1993  Date August 29, 1993  Date Consorry
Ran Tubing to 1328' and pur Casing Stub. Tagged Cemen.  Pulled Tubing to 518' Set at 404'.  Pulled Tubing and Set 50' 4' Above Surface. Weld We.  LOCATION CLEANED UP, LEVEL.  Thereby certify that the foregoing is true and correct Signed W. Hindex.  (This space for Feoeral or State office use)	mped 30 Sacks Cement, 1/2 in Casing Stubt 1225'.  Cement Plug. Pulled Tubing and Ran Back  Cement PLUG in 8-5/8" to Surface with 4-  11 Name: Amerada Federal #1, Sec. 5, T-1  ED, THEN RIPPED.  OPERATOR  Plugging of The way.	1/2" Marker Pipe Set 5S, R-30E. Lse NM 019982

RECEIVED

SEP 0 7 1993 OCD HODDS