

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON** Governor Joanna Prukop **Cabinet Secretary** 

27/03

Aspen Pumping ATT: James D Adamson 33 West Blevins Rd Artesia NM 88210

RE:

Lori Wrotenbery Director **Oil Conservation Division** 

2ND NOTICE OF VIOLATION

Property/Well <u>Walters Federal #2-L, 34-13s-30e, 30-005-20462</u>

100-677-2252

Compliance required by april 15th 2003 The enclosed forms are being returned to your company due to lack of sufficient or correct data required to properly process the forms. ALL DATA CIRCLED IN RED should be supplied or amended. Revised forms should be resubmitted. ATTACTED TO THIS FORM to the address below ATT: Donna Mull within fifteen (15) days.

<ul> <li>Plugging bond is not in place for OGRID reflected on form. Contact Dorothy Phillips in OCD</li> <li>Santa Fe Office (505) 476-3461.</li> <li>OGRID number does not exist for Operator as designated</li> <li>Proposed Bottom hole location omitted.</li> <li>Ground Level Elevation omitted</li> <li>Proposed casing record incomplete or unacceptable.</li> <li>BOP Schematic not included or attached</li> <li>Other</li> </ul>
<ul> <li>X Form is not properly signed and dated by operator only         <ul> <li>Directional Drill: Project area, producing interval, kickoff point, surface location, and bottom</li> <li>Hole location should be designated</li> </ul> </li> <li>X Acreage to be dedicated to well should be outline         <ul> <li>Non Standard location. Approved order from Santa Fe not on file.</li> <li>Non Standard proration. Approved order from Santa Fe not on file.</li> </ul> </li> <li>X Other <u>This form is required to bring this well into current status.</u></li> </ul>
<u>See NSP-1815<l>, 240 acres, E/2NW/4 &amp; SW/4</l></u> API Number omitted Proper well identification omitted Location Data incorrect or insufficient Date(s) work performed omitted Tubing size and depth and /or packer setting omitted Other