N. M. GIL band. Commanda

P. O. BOX 1980

Form 3160-5 (June 1990) UNITED STATES HOBBS, NEW MEXICO 88240
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

6. If Indian, Allottee or Tribe Name

Expires: March 31, 1993

5. Lease Designation and Serial No.
NM 15677

CHAIDDV	NOTICES	AMD	REPORTS	Ω N	WELL	S
SUNDEY	NOTICES	ANU	REPURIS	UN	WELL	3

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

7 If Unit or CA Agreement Designation

SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation	
1. Type of Well Soli Gas Well Other		8. Well Name and No.
2. Name of Operator		Hahn Federal #2
Kerr-McGee Corporation		9. API Well No.
3. Address and Telephone No.		
P. O. Box 11050, Midland, Texas 79702		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Tom-Tom - SA
		11. County or Parish, State
660' FSL & 1980' FEL, Section 27, T7S, R31E	Unit O	Chaves County, New Mexico
12. CHECK APPROPRIATE BOX(s) TO INDICATE NA	TURE OF NOTICE, REPO	RT. OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well	
13. Describe Proposed or Completed Operations (Clearly state all per	tinent details, and give pertinent dates, including estimated d	Completion or Recompletion Report and Log form.) late of starting any proposed work. If well is directionally drilled.	

- 3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
 - 1. POOH with tubing and rods.
- 2. GIH with packer and tubing. Set packer within 100' of top perforation.
- 3. Run casing test to 500 psi.
- 4. Place well on injection.

Estimated Start Date 2-10-92



14. I hereby certify that the foregoing is true and correct		·
Signed	Title Senior Staff Engineer	Date 1-17-92
(This space for Federal or State office use)		APPROVED
Approved by	Title	PETERDAW: CHESTER
Conditions of approval, if any:	SUBJECT TO LIKE APPROVAL BY STATE	JAN 2 7 1992
Title 18 U.S.C. Section 1001, makes it a crime for any person or representations as to any matter within its jurisdiction.	the state of willfully to make to any department on approx of the	United States any false, fictitious or fraudulent statements JREAU OF LAND MANAGEMENT ROSWELL RESOURCE
	*See Instruction on Reverse Side	ROSWELL RESOURCE

Swd 453

HECHAN

JAN 3 0 1992

HODES LATICE