

UNIT STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLI
(Other Instructions on Re-
verse side)

N. M. O. C. C. COPY

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM 046153-A	
2. NAME OF OPERATOR UNION TEXAS PETROLEUM CORPORATION		6. IF INDIAN, ALLOTTEE OR TRIBES NAME	
3. ADDRESS OF OPERATOR 1300 Wilco Building, Midland, Texas 79701		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit Letter "P", 660' FS&EL		8. FARM OR LEASE NAME Federal "33"	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DP, RT, GR, etc.) 4288.7' GR		10. FIELD AND POOL, OR WILDCAT Tom-Tom (San Andres)	
		11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA Sec. 33, T-7-S, R-31-E	
		12. COUNTY OR PARISH Chaves	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) Plug & Abandon.	
(Other)		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. June 22, 1977, re-entered well and pulled tubing & packer. Set CIBP at 3750' and dumped 3 sx. Class "H" cement on top.
2. June 23, 1977, loaded hole w/10# brine. Ran jet cutter and cut casing at 3010' and pulled this casing.
3. Ran tubing to 3060' & pumped 25 sx. mud. Spotted 35 sx cement plug at 3060'.
4. Set 35 sx. cement plug @ 1530'.
5. Set 35 sx. cement plug @ 450'.
6. June 25, 1977, set 5 sx. cement plug @ surface and installed dry hole marker.

NOTE: USGS will be notified when location is ready for inspection.

We are in the process of moving all equipment, leveling pits and ripping up location.

RECEIVED
JUL 05 1977
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

RECEIVED
U.S. GEOL.

18. I hereby certify that the foregoing is true and correct

SIGNED Stanley A. Reed TITLE Sr. Production Analyst

DATE 6-29-77

(This space for Federal or State office use)

APPROVED BY ALBERT R. STALL TITLE ACTING DISTRICT ENGINEER

DATE JAN 25 1980

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JAN 31 1980

OIL CONSERVATION DIV.

RECEIVED

JAN 28 1980

O. C. D.
ARTESIA, OFFICE