SUBMIT IN TRIPL.	
(Other instructions	u
verse side)	

Form approved.

(May 1963) DEPARTM	ENT OF THE INTER	IOR (Other Instructions on re-	5. LEASE DESIGNATION A NM-0558016	ND SERIAL NO.
SUNDRY NOTION (Do not use this form for propose Use "APPLICA"	CES AND REPORTS ls to drill or to deepen or plug FION FOR PERMIT—" for such	ON WELLS back to a different reservoir. proposals.)	6. IF INDIAN, ALBUTIES	-
OIL GAS OTHER		: · · ·		
2. NAME OF OPERATOR McClellan Oil Corpora	6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Cedar Point 9. WELL NO. 2 10. FIELD AND FOOL, OR WILDCAT Wildcat 11. SEC., T., E., M., OR BLE. AND SURVEY OR AREA Sec. 21-T15S-R30E 12. COUNTY OR PARISH 13. STATE Chaves N. M.			
3. ADDRESS OF OPERATOR P. O. BOX 848, ROSWell	2			
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		ł .	WILDCAT	
1980' FSL & 330' FWL 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)			Sec. 21-T15S-R30E 12. COUNTY OR PARISH 13. STATE	
14. PERSIT NO.	4011 G. L.		Chaves	N. M.
16. Check Ap		Nature of Notice, Report, or C	ENT REPORT OF:	[]
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL	ULL OR ALTER CASING ULTIPLE COMPLETE BANDON* HANGE PLANS	Completion or Recompl	ALTERING CAS ABANDONMEN of multiple completion o	r* X n Well n.)
nent to this work.) *	inally difficulty give business.	ent details, and give pertinent dates, actions and measured and true vertice. 2/77, this test was P &	•	and zones perf

on 9/14/77: 150' cement plug @ T. D. (2350-2200'), 100' plug @ 1350-1450' (Base of Salt), 100' plug @ 630-730' (Top of Salt), 20' plug @ surface. Heavy mud placed between cement plugs. Will set dry hole marker and clear location.

RECEIVED

OCT 27 1977

U.S. GEULUGICAL SURVEY ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct	Operator Operator	DATE 10/25/77
(This enace for Federal of State office ase)	TITLE ACTING DISTRICT ENGINEER	DATE MAR 2 1 1978