Submit 3 Copies to Appropriate District Offics	State of New Mexico Energy, Minerals and Natural Resources Department			- Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240		TION DIVISION	WELL API NO.	
DISTRICT II		ox 2088 exico 87504-2088	30-005-20648	
P.O. Drawer DD, Artesia, NM \$8210 DISTRICT III			5. Indicate Type of Lease STA	
1000 Rio Brazos Rd., Aztec, NM \$7410			6. State Oil & Gas Lease No	k
	ICES AND REPORTS ON	N WELLS		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agre	
(FOHM C	-101) FOR SUCH PROPOSALS	<u>3.)</u>	Chaveroo San A Tract - 6	Andres Unit
	OTHER	Injection	(Roberts Lease	: }
2. Name of Operator El Ran, Inc.			8. Well No. #1	
3. Address of Operator			9. Bool name or Wildcat	
P.O. Box 911, Lu 4. Well Location	bbock, Texas 7940	8	San Andres	
Unit Letter :44	0 Feet From The	n Line and19	80 Feet From The	east Line
Section 3	Township 8 south		NMPM Chaves	County
	10. Elevation (Show)	whether DF, RKB, RT, GR, etc.)		
II. Check	Appropriate Box to Indi			
	TENTION TO:	•	SEQUENT REPOR	
	PLUG AND ABANDON			
		CASING TEST AND C		
	·····		rted to Injection	R-TOURA -
 Describe Proposed or Completed Open work) SEE RULE 1103. 	tions (Clearly state all pertinent de	tails, and give pertinent dates, incl	uding estimated date of starting a	ny proposed
	·			
See Attachment				
	•			
	н ^н иц.			
I hardy cartify that the information phove is true MAA = MC	• • •	•		
SIGNATURE	un	_ mms Production	Analyst DATE	02/01/89
TYPE OR PRINT NAME			TELET	IONE NO.
(This space for State Use).	Orig. Signed by Paul Rautz			
	Paul Kautz Geologist		сана стана стан Стана стана стан	EB 0 6 1985

.

WORKOVER REPORT

Chaveroo Field	<u>Perfs</u> 4177'-4219' 4249'-4284'	(Roberts #1) <u>Chaveroo_Unit_Tr-6_#1</u>	
Chaves Co., N.M. TD: 4330' PBTD: 4326'		8 5/8 • 1817' 4 1/2 • 4329' 2 3/8 • 4234'	

- 01/26/88 RU Robco Well Service. Unseat pump and pulled 171-3/4" rods and pump. Pulled 139-2 3/8", 4.7#, J-55 tbg. Ran gauge ring and tagged @ 4329'. SDFN.
- 01/27/89 Ran 2 3/8" pump out plug, 2 3/8" seating nipple w/ changeover, 2 3/8" x 4 1/2" Guiberson hydraulic set isolation pkr, 4 jts of 2 3/8", 4.7#, J-55 Salta lined tbg, 2 3/8" x 4 1/2" Guiberson ER-VI pkr, 2 3/8" x 4 1/2" Type "XL" on/off tool, and 133 jts of 2 3/8", 4.7#, J-55 Salta lined tbg. Pump 7 bbls of treated pkr fluid down backside. Set top pkr e 4108'. Pressure up backside w/ 36 bbls treated pkr fluid to 500 psi. Held for 30 mins. OCD representative was present. Rig upon tbg and pressure tbg to 1280 psi and sheared out the pump out plug and set hydraulic pkr • 4234'. Pumped 8000 gals 20% NEFE Hcl acid dwn tbg at 3 BPM. Flush w/ 20 bbls fresh wtr. Max TP: 20 psi, Min TP: 0 psi, ISIP: vac. Hooked up injection wellhead assembly. RD service unit. WELL WAS CONVERTED FROM PRODUCER TO INJECTOR. FINAL REPORT. Began injecting 1/30/89.