## N.M.O.C.D. COPY

(May 1963) UNIEL TATES SUBMIT IN CONTROL (Other instru	
DEPARTMENT OF THE INTERIOR (Other Instru	5. LEASE DESIGNATION AND SERIAL NO.
GEOLOGICAL SURVEY	NM 8255
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	
(Do not use this form for proposals to drill or to deepen or plug back to a different re Use "APPLICATION FOR PERMIT—" for such proposals.)	servoir.
1. OIL GAS 57	7. UNIT AGREEMENT NAME
WELL GAS WELL OTHER	
2. NAME OF OPERATOR	S. FARM OR LEASE NAME
Petroleum Exploration & Development Funds, Inc.	Cockrell-Federal
3. ADDRESS OF OPERATOR	9. WELL NO.
D O Drover 35/7 Midland TV 70702	#1
P. O. Drawer 3547, Midland, TX 79702  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*	
See also space 17 below.)	
At surface	Undesignated - Morrow 11. SEC., T., R., M., OR BLE, AND
	SURVEY OR AREA
660' FNL and 1980' FWL	1/ m 1/ c p 20 F
	14, T-14-S, R-30-E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
3908 G.L.	Chaves Texas
	0.1.0.
Check Appropriate Box To Indicate Nature of Notice,	Report, or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
	X REPAIRING WELL
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-	
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TR	EATMENT ALTERING CASING
SHOOT OR ACIDIZE ABANDON* SHOOTING OR	ACIDIZING ABANDONMENT*
REPAIR WELL CHANGE PLANS (Other)	
(Other) (NOTE:	Report results of multiple completion on Well tion or Recompletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give p proposed work. If well is directionally drilled, give subsurface locations and measured a nent to this work.) *  1-13-80	and true vertical depths for all markers and zones perti-
T.D/ 2526'. 11" Hole. Ran 8 Joints - 336' of 8-5/8" 2190' of 8-5/8" - 24# - K-55 Csg. w/Guide Shoe @ 2526 DV Tool @ 1602'. Cement 1st stage w/250 Sx Class 'C' and circ. 25 Sx Cement to surface. Cement thru D.V. w/1/4# flo Cele and 12# Salt per Sx. plus 150 Sx 'C' Surface. Nipple up and W.O.C. 8 hours, test csg. to o.k. Drill out D.V. tool and test to 1500 p.s.i h7-7/8".	5', Float Collar @ 2484', and w/2% CaCl 2, open D.V. tool tool @ 1602' w/550 Sx Howco Lite w/2% CaCl 2. Circ. 150 Sx to 1500 p.s.i. for 30 min held
Jāli	16.2
U. Ş. HELLO ARTEŞIA,	140 - 42 CO.N. EY N.E.V. M.E.XI.30
18. I hereby certify that the foregoing is true and correct  SIGNED	intendent DATE 1-17-80
(Mills and And Theland on State office use)	
(This space for Federal or State office use)  APPROVED (Cris. Sed.) GEORGE E. STEWART  TITLE	- (
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	DATE

OIL CONSERVATION DIV.

BECEINED

0861 13 NAU

JAN 2 8 1980

RECEIVED

O, C. D.