

L CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.M.	
CARD OF FILE	
OPERATOR	

4. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REFINISH OR PLUG BACK TO A DIFFERENT RESERVOIR.
SEE REGULATION AND PERMIT OF LCONSA C-1013 FOR SUCH PROPOSALS.

1. Name of Operator Fred Pool Drilo. Inc.	7. Unit Agreement Name
2. Address 11 Clovis Star Rt. Roswell, N.M. 88201	8. Farm or Lease Name Opal
3. Location of Well UNIT CENTER P 660 FEET FROM THE S LINE AND 660 FEET FROM THE E	9. Well No. 1
4. Location of Well THE E 1/4 SECTION 33 TOWNSHIP 8 RANGE 32E NEPHE	10. Field and Pool, or Whichever Indesignated
15. Elevation (Show whether DF, RT, GR, etc.) 4378.6L	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-10-80

Swabbed back water, three days.

~~Intend to plug and abandon.~~

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Secretary</u>	DATE <u>2-17-81</u>
APPROVED <u>[Signature]</u>	TITLE <u>MANAGER DISTRICT</u>	DATE <u>1981</u>
CONDITIONS OF APPROVAL, IF ANY:		

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-76

RECEIVED

JUL 14 1980

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-4409

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DEPTH. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

O.C.D.
ARTESIA, OFFICE

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
Name of Operator Fred Pool Drllg, Inc.
Address of Operator 437 White Bldg. Roswell, N.M. 88201
Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>33</u> TOWNSHIP <u>8-S</u> RANGE <u>32-E</u> N.M.P.M.

7. Unit Agreement Name
8. Farm or Lease Name Opal
9. Well No. 1
10. Field and Pool, or Wellcat Undesignated
11. Elevation (Show whether DF, RT, GR, etc.) 4378 1/2 G.L.
12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>2nd perforation and Acidize</u> <input checked="" type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-27-80 Pulled Tubing out of well
7-1-80 Drilled out cement retainers
7-2-80 Perforated at 4229-4231. 2 Shots per foot.
Ran packer and spotted acid at 4224', pulled one joint and set packer at 4204'. Treated well with 32 barrells of NE 20% Acid and 40 barrells of water. Well went on vacuum and swabbed 24 hrs. Showed 30% oil, 70 % oil.
Flood level stayed at 3000 feet.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Tate Jones TITLE Secretary DATE 7-11-80

APPROVED BY James L. Taylor TITLE SUPERVISOR DISTRICT 1 DATE JUL 16 1980

CONDITIONS OF APPROVAL, IF ANY: