

RECEIVED BY  
Form 9-331  
Dec. 1973

OCT 04 1984

O. C. D.

ARTESIA OFFICE

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

NM OIL CONS. COMMISS

Drawer DD

Artesia, NM 588216

Form Approved.  
Budget Bureau No. 42-R1424

NM 31263

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Holbrook-Federal "B" *Federal*

9. WELL NO.

3

10. FIELD OR WILDCAT NAME

Vest Ranch-On. Assoc.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

9-15S-30E

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

4033 KB

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐

2. NAME OF OPERATOR

Dalport Oil Corp.

3. ADDRESS OF OPERATOR 3471 ~~First National~~ *Inter First One*

~~Bank Bldg.~~, Dallas, Tx 75202

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 660' FSL, 1650' FWL

AT TOP PROD. INTERVAL: same

AT TOTAL DEPTH: same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON\* ☒

(other) ☐

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Old info: TD 2365, PBTD 2342, 8-5/8 - 24# at 304'; 4-1/2 - 9.5# at 2365 w/275 Sx; 2289-93 2-3/8" - 4.7# at 2279.5; 1' S.N., 3' perf nipple, 6' M.A.

Intend to plug as follows: *2343'-2243'*

100' plug (15 sx) ~~2193-2293~~, tag plug; will cut casing at approx.

1500'. 100' plug (20 sx) 1450' - 1550 (in and out of stub), tag plug;

100' plug (20 sx) 250'-350', tag plug; 10 sx - surface, clean location. Set 4' marker with name location of well. *FWC.*

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Dean M. Lampert*

TITLE

Geologist

DATE

9-17-84

APPROVED

(This space for Federal or State office use)

APPROVED BY

(Orig. Sgd.) PETER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

OCT 1 1984



\*See Instructions on Reverse Side