

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

L CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Western Reserves Oil Company	8. Farm or Lease Name RMM
3. Address of Operator P. O. Box 993, Midland, TX 79702	9. Well No. 2
4. Location of Well UNIT LETTER <u>0</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>29</u> TOWNSHIP <u>7S</u> RANGE <u>31E</u> NMPM.	10. Field and Pool, or Wildcat Tom-Tom (San Andres)
15. Elevation (Show whether DF, RT, GR, etc.) 4288.6' GR	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/12/80 Spud 12 1/4" hole @ 12:45 p.m.

11/13/80 Casing point 1350'. Ran 31 jts 8 5/8" 24# K-55 ST&C casing. (1358' set @ 1348') Cemented w/500 sx Hal-lite, 1/4# flocele/sx, 5# gilsonite/sx, 2% CaCl₂, followed by 200 sx Class 'C', 2% CaCl₂. Full circulation throughout job. Circ 75 sx to surface. POB 2:30 p.m. 11/13/80. WOC 18 hrs. Pressure tested csg to 1000 psi for 30 mins.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Jerry Franklin</u>	TITLE <u>Agent</u>	DATE <u>11/17/80</u>
Orig. Signed By Jerry Sexton Dist 1, Santa Fe	TITLE	DATE <u>NOV 20 1980</u>
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		