ERGY AND MIMERALS DEPARTMENT  C. CONSERVATION DIVISION  DISTRIBUTION  P. O. BOX 2088  SANTA FE, NEW MEXICO 87501	Form C-103 Revised 10-1-78
U.S.O.S.  LAND OFFICE  OPERATOR  Reuse d	State State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OFFPEN OR PLUG BACK TO A DIFFERENT RESERVOIR,  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
WELL OTHER-	8. Farm or Lease Name
Armstrong Energy Corportion	Sara 9. Well No.
P.O. Box 1973- Roswell, NM 88201	10. Field and Pool, or Wildcat
THE East LINE, SECTION 3 TOWNSHIP 11S RANGE 31E NA	
15. Elevation (Show whether DF, RT, GR, etc.) 4514 GL.	12. County Chaves
Check Appropriate Box To Indicate Nature of Notice, Report or NOTICE OF INTENTION TO:	Other Data ENT REPORT OF:
FORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  4PORARILY ABANDON COMMENCE DRILLING OPNS.  CHANGE PLANS CASING TEST AND CEMENT JQB	ALTERING CASING PLUG AND ABANDONMENT
OTHER	
Proposed to plug and abandon, as follows:  Fill hole with mud-laden fuild. Set C.I.B.P. at 41!  Perforate @ 1480 and squeeze 50 sx. cement. Spot plug 100 to surface. Install dry hole marker. Cle	50° with 5 sx. cement.
	TOMMISSION MUST BE NOTITED 2 TO THE BENEVIAMING OF CHERATIONS FOR THE C-103 METROVELS

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPPRYISOR
TITLE

Agent

Agent

AUG 1 1983

HOSBS OFFICE

. .