

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator Armstrong Energy Corporation	8. Farm or Lease Name Sara
3. Address of Operator P.O. Box 1973 - Roswell, NM 88201	9. Well No. #1
4. Location of Well UNIT LETTER <u>J</u> , <u>1980</u> FEET FROM THE <u>south</u> LINE AND <u>1980</u> FEET FROM THE <u>east</u> LINE, SECTION <u>3</u> TOWNSHIP <u>11S</u> RANGE <u>30E</u> NMPM.	10. Field and Pool, or Wildcat Tower-San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4514' GL	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed to plug and abandon, as follows:

Fill hole with mud-laden fluid.
Spot 20 sx. cement plug @ 4210'-3915'.
Cut and pull 4-1/2" casing at 2500'±.
Spot 35 sx. cement plug @ 2550'-2414'.
Spot 30 sx. cement plug @ 2220'-2103'.
Spot 30 sx. cement plug @ 1480'-1363'.
Spot 10 sx. cement plug 100' to surface.
Install dry hole marker. Clean location.

RECEIVED
OIL CONSERVATION DIVISION
SANTA FE, NEW MEXICO
DEC 10 1982

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wes Sexton TITLE Agent DATE 12/8/82

APPROVED BY JERRY SEXTON TITLE DISTRICT MGR. DATE DEC 10 1982

PROPOSED PLUG AND ABANDONMENT

Well No. 1


Armstrong Energy Corporation

1980' FSL & 1980' FEL

Sec. 3, T-11S, R-30E

Chaves County, New Mexico

Dry Hole Marker



1474' - 8-5/8", 24#, K-55, ST&C

Surface shoe plug

FORMATION TOPS:

Yates - 2222'

Seven Rivers - 2348'

Queen - 2938'

San Andres - 3494'

4-1/2" cut off @ 2500'±

Est. TOC @ 2800'

Perfs: 4132'-4203'

4265'-4-1/2", 10.5#, K-55, ST&C.