

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

Revised

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>
--	-----------------------------------	--------------------------------

Name of Operator
Armstrong Energy Corporation
Address of Operator
P.O. Box 1973 - Roswell, NM 88201

7. Unit Agreement Name
8. Farm or Lease Name Sara
9. Well No. #2
10. Field and Pool, or Wildcat Tower- San Andres
12. County Chaves

UNIT LETTER **K**, **1980** FEET FROM THE **South** LINE AND **1980** FEET FROM
THE **West** LINE, SECTION **3** TOWNSHIP **11S** RANGE **31E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
4509.5' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
WELL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed to plug and abandon, as follows:

Fill hole with mud-laden fluid. Set C.I.B.P. at 4100' with 5sx.cement
Perforate @ 1480' and squeeze 50 sx. cement. Spot 10 sx. cement
plug 100' to surface. Install dry hole marker. Clean location.

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE OIL
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Jerry Sexton* TITLE Agent DATE July 29, 1983

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG 1 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JUL 29 1983
C.C.D.
HOBBS OFFICE