STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

HO. OF COPIES RECEIVED				
DISTRIBUTION				
SANTA FE				
FILE		l		
U.S.G.S.				
LAND OFFICE				
OPERATOR				

OIL CONSERVATION DIVISION P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103 Revised 10-1

FILE		Sa. Indicate Type of Leuse
U.S.G.S.		State X Fee
LAND OFFICE		5. State Oil & Gas Lease No.
OPERATOR		•
		LG 0342
	CHARDY NOTICES AND REPORTS ON WELLS	
IDO NOT USE THIS	SUNDRY NOTICES AND REPORTS ON WELLS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. 16 "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)	
	IL "APPLICATION FOR PERMIT -" (FORM C-[01] FOR SUCH PROPOSACES)	7. Unit Agreement Name
۱. حب رم	. —	
WELL X	S OTHER-	8. Farm or Lease Name
2. Name of Operator		
Me	redith Smith	Meredith Smith Stat
3. Address of Operator		9. Well No.
1.2	10 S. Main, Lovington, New Mexico 88260	1
	10 5. Harn, hovington, her renzes	10. Field and Pool, or Wildcat
4. Location of Well		
E	. 1980 FEET FROM THE NOTTH LINE AND 660 FEET FROM	Caprock Queen
ONIT CETTER		VIIIIIIIIII
Most	LINE, SECTION 16 TOWNSHIP 15S RANGE 31E NMPM.	
THE WEST	LINE, SECTION TOWNSHIP	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
		Chause (IIIIII)
	4414.6' GL	Chaves ()
16.	Check Appropriate Box To Indicate Nature of Notice, Report or Oth	ier Data
	TICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
NO.	TICE OF INTENTION TO:	
		ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ASANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
1		
OTHER		
17 December Proposed of	Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any propo
work) SEE RULE 11	33,	

As per approval from Eddie Seay of the NMOCD (date undnown), Baber Well Service plugged the well as follows: (7-11-83 - 7-14-83)

Pulled pkr and tbg. Ran CIBP on wireline and set it at 3100'. Ran tbg; mudded hole. Dumped 100' cement plug - tagged 0.K. Cut and pulled 28 jts. of $5\frac{1}{2}$ " csg. Set 100' cement plug at 2400'. Set 50 sxs cement plug at 1120'. Next a.m. tagged plug at 916' spotted 50 sxs cement at 394'. Tagged plug at 269'. Spotted 10 sx. Surface plug. Installed dry hole marker. Job complete.

18. I hereby certify that the information above is true and compl-	ete to the best of my knowledge and belief.	
sience Sphan Africhant	TITLE Consulting Pet. Eng.	DATE 10/19/83
M V Morchant		- 4000

Jurnaeliff OIL & GAS INSPECTOR

NOV 1 1983