		Drawer DD	
Stress SUBMIT IN TRIPLIC May 1963) DEPARTMENT OF THE INTERIOR verse side)		VTERIOR (Other Instructions on I	5. LEASE DESIGNAT (N AND SERIAL NO.
(Do not use this t	GEOLOGICAL SURV ORY NOTICES AND REPO Use "APPLICATION FOR PERMIT-"	RTS ON WELLS	B. IF INDIAN, ALLO THE OR TRIBE NAME
1.	······································		7. UNIT AGREEMEN NAME
2. NAME OF OPERATOR	OTHER .	NOV 09 1984	8. FARM OR LEASE NAME
MOTOILCO, I 3. ADDRESS OF OPERATOR	nc.	O. C. D. ARTESIA, OFFICE	Mazie Federal
Drawer I, Artesia NM 88210 LOCATON OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		#1 10. FIELD AND FOOL, OR WILDCAT East Sitte 11. SEC., T., B., W. DE BLK. AND	
330 FNL	1980 FWL	Unit C	SURVEY OR ALKA
14. PERMIT NO.	15. ELEVATIONS (Show w	/hether DF. RT. GR, etc.)	23-8-31 12. COUNTY OR PAUSH 13. BTATE Chaves NM
16.		licate Nature of Notice, Report, or	Other Data
TENT WATER SHUT-OF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE TROPOSED OR proposed work. If nent to this work.)* 12 '22 '82 Set 1382 appr with Set	MULTIPLE COMPLETE ABANDON* CHANGE PLANS COMPLETED OPERATIONS (Clearly state all well is directionally drilled, give subsur Plug & abandoned well BP @ 2030, set 35' of (5 holes). Squeeze coximately 30 sx. to 2 3 8" tubing. Pur dry-hole marker, lev	Dertinent details, and give pertinent data face locations and measured and true ver and from 1378 - 1382 w cover salt section W mped 10 sx. to surface veled location and le Armondo Lopez. (12	with 100' of cement, w.O.C. Tag at 1270 we & circulated. weled pit.
•	The design of the second correct		PN 2 THE E
18. I hereby certify that SIGNED	the foregoing is true and correct	Operator	DATE 12 23 82
		°LE	DATE
		structions on Reverse Side	

i

p207770

NOV 1 3 1984

1 . .