(May 1963) DEPARTI	UNITE. STATES WING CITEMPT'IN TESTS DEPARTMENT OF THE INTERIOR (Other instruction of the		5. LEASE DESIGNATION AND SERIAL NO.		
SUNDRY NOT (Do not use this form for propor Use "APPLICA	ICES AND REPORTS O	N WELLS ack to a different reservoir.	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME	
i.			7. UNIT AGREEMENT NAS	ME	
OIL GAS WELL OTHER 2. NAME OF OPERATOR			8. FARM OR LEASE NAME		
Roy G. Barton Jr.			Betty Federal		
3. ADDRESS OF OPERATOR P. O. Box 978 Hobbs, New Mex. 88240			9. WELL NO.		
4 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*			10. FIELD AND POOL, OR WILDCAT		
See also space 17 below.) At surface 660' FNL & 990' FWL Unit "D"			SE Chaves Queen Area 11. BEC. T. S. W. OF BLK. 1MD SURVEY OF AREA		
			Sec. 3-14S	30E.	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, 3848 G1.	RT, GR, etc.)	12. COUNTY OF PARISH Chaves	13. STATE New	Mex.
16. Check A	ppropriate Box To Indicate N	ature of Notice, Report, or C	Other Data		
NOTICE OF INTENTION TO:			QUENT REPORT OF:		
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS	(Many Benest regult	REPAIRING WALTERING CALTERING CALTER	ASING NT* X on Well	
Well was spudde	ERATIONS (Clearly state all pertinent ionally drilled, give subsurface located by the subsurface	L983 and drilled was run to 560' a	to a depth of nd Cemented v	E 560', with	
pits. Plug do	wn at midnight and	d shut down waiti	ROSE OST ON A		
SIGNED (This space for Federal of State of APPROVED BY CONDITIONS OF APPROVALLIE	inchibe TITLE	Geologist	DATE	XICO 10-1983	



