

P. O. BOX 1130
HOBBS, NEW MEXICO 88240

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other P&A	5. Lease Designation and Serial No. NM 18503
2. Name of Operator YATES PETROLEUM CORPORATION (505) 748-1471	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. 105 South 4th St., Artesia, NM 88210	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit M, 330' FSL, 330' FWL, Sec. 1-T8S-R31E	8. Well Name and No. Center XI Federal #4
	9. API Well No. 30-005-20936
	10. Field and Pool, or Exploratory Area Tomahawk SA
	11. County or Parish, State Chaves, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged and abandoned well as follows:

1-23-92. RU. ND wellhead. Pull out with 2' sub. NU BOP. RIH with wireline. Set CIBP at 3924' and cap w/5' sx cement on top. RIH with tubing to 3925'. Circulate hole with mud. POH with tubing. RIH w/wireline. Cut 4 1/2" casing at 2100'. POH and lay down 2100' of 4 1/2" casing. RIH with tubing to 2140'. Spot 60 sacks plug. POH with 10 stand. WOC 4 hrs. RIH. Tag plug. No plug. Spot another 60 sacks. Pull 10 stands. SD for day. RIH with tubing. Tag stub plug at 1950'. POH with tubing to 1617' and spot 90 sacks cement. Shoe plug and pull 10 stands tubing. WOC 4 hrs. RIH with tubing. Tag plug at 1350'. POH with tubing to 400'. Spot 30 sx cement at 400'. POH with tubing to 37'. Circulate cement to surface. Dug out cellar. Cut off wellhead. Install dry hole marker. Clean location and move off. Plugging completed 1-28-92.

14. I hereby certify that the foregoing is true and correct

Signed Peter W. Chester
(This space for Federal or State office use)

Title

APPROVED
PETER W. CHESTER
MAR 27 1992
BUREAU OF LAND MANAGEMENT
ROSWELL RESERVATION

Date

12-8-92

Approved by _____
Conditions of approval, if any:

Approved on plugging of the well bore.
Likely water base is retained until
surface restoration is completed.

Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side