

(JUNE 1990)

UNITED STATES -  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division  
1625 N. French Dr.  
Hobbs, NM 88240  
FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals of drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT -" FOR PROPOSALS

**SUBMIT IN TRIPLICATE**

## 1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

## 2. Name of Operator

CIRCLE RIDGE PRODUCTION, INC.

## 3. Address and Telephone No.

1008 W. BROADWAY, HOBBS, NM 88240 505-393-2727

## 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UNIT A, SEC. 3, T13S, R31E  
330' FNL & 990' FEL

## 5. Lease Designation and Serial No.

NMNM20968

## 6. If Indian, Allottee or Tribe Name

## 7. If Unit or CA, Agreement Designation

## 8. Well Name and No.

TAO-FEDERAL #2

## 9. API Well No.

30-005-20964

## 10. Field and Pool, or Exploratory Area

CAPROCK QUEEN

## 11. County or Parish, State

CHAVES CO., NM

## 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form)

## 13. Describe Proposed or Completed Operations (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

06/06 & 06/07/00 Notify BLM, MIRU. POOH w/114 rods, NU BOP. POOH w/94 jts tbg. Set CIBP  
@ 2900', Circ 10# mud to surf. & Spot 15 sxs cmt on top CIBP. Spot 20 sxs @ 2000'-1800' & 20 sxs  
604'-404' & 10 sxs 60' to surf. Cut off wellhead, level pit & cellar. Install dry hole marker.

Worked as to plugging of the well BOP.  
Well to water head is retained until  
surface restoration is completed.

## 14. I hereby certify that the foregoing is true and correct

Signed

*Ray Heard*

Title

AGENT

Date

08/31/00

(This space for Federal or State office use)

ORIG. SGD.) DAVID F. GLASS

Approved by

Title

PETROLEUM ENGINEER

Date

OCT 18 2000

Conditions of approval, if any:

LC

GWW