

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.  
30 005 21010

Indicate Type of Lease  
STATE ☒ FEE ☐

State Oil & Gas Lease No.  
K05606

Lease Name or Unit Agreement Name  
STATE DQ

Well No.  
2

Pool name or Wildcat  
BLINEBRY

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:  
OIL WELL ☐ GAS WELL ☐ OTHER WORKOVER - P&A

Name of Operator  
SOUTHWEST ROYALTIES, INC. ATTN: BEVERLY HATFIELD

Address of Operator  
P. O. BOX 11390; MIDLAND, TX 79702

Well Location  
Unit Letter D : 330 Feet From The NORTH Line and 840 Feet From The WEST Line  
32 Section 9S Township 30E Range NMPM CHAVES County

Elevation (Show whether DF, RKB, RT, GR, etc.)  
4043 GL

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: WORKOVER UNSUCCESSFUL - P & A ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-10-98 MIRU PU; WORK TBG TRYING TO PULL FREE; WOULD NOT COME FREE; PULL 20,000# OVER WEIGHT.

3-11-98 RAN FREE POINT & TAG RODS @ 6622'; BACK OFF @ 6561'.

3-12-98 RIH W/199 JTS 2-7/8" TBG; SET RET @ 6520'; PMP 200 SXS "C" NEAT 14.8 PPG @ 1-1/2 BPM; STING OUT OF RET; PULL TO 5661'.

3-13-98 RIH W/4" CSG GUN AND PERF 5627-34' (14 HOLES); 5576-84' (16 HOLES); 5560-64' (8 HOLES); 5186-94' (16 HOLES); 4928-40' (24 HOLES); 4750-56' (12 HOLES).

3-14-98 ACID TREAT 5560-5634' W/3000 GALS 15% NEFE HCL; SWABBED ALL WTR.

3-17-98 TREAT PERFS @ 4928-40' & 5186-94' w/1000 gals 15% NEFE; SWABBED ALL WTR.

3-19-98 SET CIBP @ 4700'; DUMP 35' OF CMT ON TOP; PERF SAN ANDRES 3441-3402', AT W/3000 GALS 15% NEFE HCL.

3-24-98 SET CIBP @ 3360'; CIRC HOLE W/63 BBLs 10# MUD. SPOT 2 BBLs CMT ON TOP ON CIBP; SPOT 38 cu ft CMT PLUG FROM 852-1000'; SPOT 10 SX SURF PLUG; CUT OFF WELL HEAD & WELD DRY HOLE MARKER. CLEANED LOCATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Beverly Hatfield TITLE COMPLIANCE SPECIALIST DATE 04-02-98

TYPE OR PRINT NAME BEVERLY HATFIELD

TELEPHONE NO. 915 686-9927

(This space for State Use)

APPROVED BY Billy E. Pruett TITLE  DATE

CONDITIONS OF APPROVAL, IF ANY:

see also New Mexico Public Lands Commission