

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 005 21011
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	K05606
7. Lease Name or Unit Agreement Name	State DQ
8. Well No.	3
9. Pool name or Wildcat	SWD Wolfcamp
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER SWD	2. Name of Operator Southwest Royalties, Inc.
3. Address of Operator P.O. Box 11390, Midland, Tx. 79702	4. Well Location Unit Letter G : 2305 Feet From The North Line and 2290 Feet From The East Line Section 32 Township 9S Range 30E NMPM Chaves County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. 7/22/98 notify OCD of move in
2. 7/22/98 set CIBP @7240
3. 7/23/98 circulate well w/9.8#mud spot 25sx.cmt.@7240 to 6993
4. 7/23/98 spot 25 sx.cmt.@4134 to 3881
5. 7/23/98 spot 25 sx.cmt. @954 to 707
6. 7/23/98 spot 5sx.cmt. @30 ft. to surface
7. 7/25/98 cut off well head install dry marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Wayne Brooks TITLE PLUGGING SUPT. DATE 7/25/98
TYPE OR PRINT NAME WAYNE BROOKS TELEPHONE NO. _____

(This space for State Use)

APPROVED BY Bill E. Pugh TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

ICSGHWW

ch