

N. M. OIL CONS. COMMISSION
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

P. O. BOX 1980

PERMIT IN COMPLIANCE WITH
N.M. OIL CONSERVATION ACT
(Other Instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-15895

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Carson Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 3, T-9-S, R-31-E

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

1.

OIL ☐ GAS ☒ OTHER ☐
WELL WELL WELL

2. NAME OF OPERATOR

Robert N. Enfield

3. ADDRESS OF OPERATOR

P. O. Box 2431, Santa Fe, New Mexico 87501

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

1980' FSL & 990' FWL of Sec. 3

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4277.5 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Completion Procedure:

Completion work will begin approximately October 22, 1985. Procedure is as follows:

- 1.) Move in and rig up completion equipment.
- 2.) Go in hole and spot acid.
- 3.) Perforate the Atoka zones as follows:
 - a.) 9403', 05', 07', 09', 13', 14', and 15' K.B. (7 holes).
 - b.) 9420', 21', 22', 23', 24', 25', and 26' K.B. (7 holes).
- 4.) Swab test.
- 5.) Retreat and swab and/or flow test.
- 6.) Run Potential test.

18. I hereby certify that the foregoing is true and correct

SIGNED

Sheyl A. Cool

TITLE Agent

DATE 10/18/85

(This space for Federal or State office use)

APPROVED BY

APPROVED

CONDITIONS OF APPROVAL OF AN

TITLE

DATE

OCT 23 1985

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side

RECEIVED
OCT 24 1985
O.C.M.
HOBBS OFFICE