

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-1348

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Cola ADO State Com
3. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Well No. 2
4. Location of Well UNIT LETTER <u>E</u> <u>1880</u> FEET FROM THE <u>North</u> LINE AND <u>760</u> FEET FROM THE <u>West</u> LINE, SECTION <u>31</u> TOWNSHIP <u>8S</u> RANGE <u>33E</u> NMPM.	10. Field and Pool, or Wildcat Bar U Penn
15. Elevation (Show whether DF, RT, CR, etc.) 4394.6' GR	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Intermediate casing</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-15-87. Ran 89 joints 8-5/8" 32# J-55 casing set 3870'. 1-Texas Pattern Notched guide shoe set 3870', float collar set 3826'. Cemented w/1100 sx Pacesetter Lite with 5# salt and 1/4# celloseal. Tailed in with 250 sacks Class "C" Neat (1.32 yield; 14.8 weight). PD 4:45 PM 6-15-87. Bumped plug to 2000 psi, released pressure and float held okay. Cement circulated 105 sacks. WOC. Drilled out 10:45 AM 6-16-87. WOC 18 hrs. NU and tested to 1000 psi, OK. Reduced hole and resumed drilling.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Paul Kautz</u>	TITLE <u>Production Supervisor</u>	DATE <u>6/25/87</u>
Orig. Signed by <u>Paul Kautz</u> Geologist	TITLE _____	DATE <u>JUL 1 1987</u>
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED
JUN 30 1987
OCD
HOBBS OFFICE