I""TED STATES DEPARTI. IT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

FORM APPROVED

N.M. C.. Cons. Division MB No. 1004-0135

1625 N. Frenchal Ferial No.

Hobbs, NM	88240
-----------	-------

6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other Instructions on reverse side 8. Well Name and No. Type of Well Gas Well Other X Oil Well Vest Ranch RE Federal #2 9. API Well No. Name of Operator 30-005-21140 Yates Petroleum Corporation 10. Field and Pool, or Exploratory Area 3b. Phone No. (include area code) 105 S. 4th Street - Artesia, NM 88210 505-748-1471 **Undesignated Wolfcamp** 4. Location of Well (Footage, Sec., T.,R., M., or Survey Description) 11. County or Parish, State 330' FNL and 1650' FWL Section 21 T14S-R30E Chaves County, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUMISSION Production (Start/Resume) Water Shut-Off X Acidize Deepen Notice of Intent Reclamation Well Integrity X Alter Casing Fracture Treat X Subsequent Report X Recomplete X Other Final Abandonment Notice Casing Repair New Construction Perforate Temporarily Abandon Change Plans Plug and Abandon Plug Back Water Disposal Convert to Injection 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operations results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspecition.) 10/26/00 - Set RBP at 8009'. 10/27/00 - Perforate Wolfcamp 7894-7904' with 44 holes, .41". 10/30/00 - Acidize perfs 7894-7904' with 2050 gals 15% IC HCL. 11/9/00 - Acidize Wolfcamp perfs 7894-7904' with 5000 gals 15% IC HCL + 63 tons CO2. 11/9-11/14/00 - Swab test. 11/15/00 - TIH with coiled tog to clean out to RBP at 8009'. Tagged up at 7862'. FEB 2 8 2002 11/20/00 - Impression block shows casing may be collapsed. 11/21/00 - TIH with swedge to 7868', quit going. TOH, did not have swedge. 11/22-11/30/00 - Attempt to retrieve swedge, did not recover. NDO A, LOPEZ 12/1/00 - Rig down, move out. Recompletion attempt was unsuccessful. PETROLEUM ENGINEER I hereby certify that the foregoing is true and correct Name (Printed/Typed) **Engineering Technician** Susan Herpin Date Signature 25-Feb-02 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Date Title Approved by Office Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any