

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-005-21160
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	DULCE '36' STATE COM
8. Well No.	1
9. Pool Name or Wildcat	Wildcat (Gas) ANDERSON RANCH WEST MORROW

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.	
1. Type of Well:	OIL WELL ☐ GAS WELL ☒ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>F</u> : <u>1330</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line Section <u>36</u> Township <u>15-S</u> Range <u>31-E</u> NMPM <u>CHAVES</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4352'

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐ INTERMEDIATE CASING ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-08-00/ 8-13-00: DRLG 4472-4498. RUN 9 5/8" CSG, FLOAT SHOE @ 4498. 1 SHOE JT 40# C95 LTC 47.62' INSERT FLOAT @ 4449, 20 JTS C95 LTC 911', 78 JTS J-55 LTC 3541'. TOTAL PIPE 4501', 10 CENTRALIZERS BOTTOM 900'. CMT W/DSS 1500 SX LEAD & 700 SX TAIL. CIRC 400 SX. PLUG DOWN @ 3:00 AM 7-07-00. NDOB. SET CSG SLIPS W/150,000. NUBOP. DRILL 4432-4498, 4565, 5032, 5280, 5532, 5850, 6034, 6087, 6115, 6595, 6760, 7114, 7260, 7595, 7760, 8150, 8231, 8660, 8701, 8864, 9030, 9174, 9218, 9232, 9237, 9390, 9499, 9527, 9623, 9997, 10,122, 10,160, 10,239, WORK STUCK PIPE @ 10,239. RUN FREE POINT @ 10,100. ATTEMPT TO BACK OFF @ 9932. BACK OFF DCS @ 9932. TIH BACK TO FISH @ 9932. TIH W/FISHING TOOLS TO 9839, 3 JTS ABOVE FISH. WASH DOWN 93' TO TOP OF FISH. CATCH FISH. REL FSH. CIRC & COND MUD @ 9927. TIH W/SNKR BAR TO BIT @ 10,239. JAR ON FISH. WASH 220' TO BTM W/8' SOFT FILL. DRILLING 10,239-10,397, 10,504, 10,825, 10,892, 11,040, 11,263, 11,377, 11,595, 11,702, 11,800, 11,996, 12,148, 12,197, 12,298, 12,391, 12,607, 12,693, 12,751, 12,912, 12,942. TD @ 10:00 AM 8-10-00. WASH & REAM 60' TO BTM. INSTL FLOW LINE. RU LOGGERS RAN BOREHOLE COMPENSATED SONIC GAMMA RAY 12,875-4488, & PLATFORM EXPRESS 12,920-4488, & FMI, & MSCT(SIDE WALL CORES) 12,609-12,532, 11,486, 9,826-9,731, 6121', 5666, 4820, 4757-4572. TIH TO 12,942' NO FILL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 8/14/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY: _____ TITLE _____

DATE _____

DeSoto/Nichols 12-93 ver 1.0

Orig. Signed by
J. Denise Leake
Engineering Assistant

MAR 26 2001