DISTRICT 1 P. O. Box 1980, Hobbs, NM 88240

Г

DISTRICT II P. O. Drower DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM B7410

DISTRICT IV P. O. Box 2088, Santa Fe, NM 87504-2088 State of New Mexico Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

PO Box 2088 Santa Fe, NM 87504-2088 Form C-102 Revised February 10, 1994 Instructions on back

Submit to Appropriate District Office

State Lease-4 copies

Fee Lease-3 copies

WELL LOCATION AND ACREAGE DEDICATION PLAT

Dilolcat -Undesignated, Morrow 30-005-21160 ²Pool Code ³ Pool Name (G45 97085 Well Number Property Code ⁵Property Name Dulce "36" State Com. 1 80perator Nor Elevation OGRID No. TEXACO EXPLORATION & PRODUCTION, INC. 4342' 22351 ¹⁰ Surface Location Feet from the North/South line Lot Idn East/West line County Feet from the UL or lot no. Section Township Range 1980' 31-E North 1980' Chaves West F 36 15-S 11 Bottom Hole Location If Different From Surface Range Feet from the East/West line ⁷County UL or lot no. Section Township Lot Idn Feet from the North/South line 12Dedicated Acres ¹³Joint or Infill ¹Consolidation Code 15Order No. 320 NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION. 'OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the sest of my knowledge and belief. Δ Signature Hill Lyon 1980' Ĩ Printed Name A. Phil Ryan Position Commissioner Coordinator Campany – 1980' – Texaco Expl. & Prod. Inc. Date State Com. #1 Elev. 4342' June 6, 2000 "SURVEYOR CERTIFICATION 36 I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my knowledge and belief. Date Surveyed June 5, 2000 Signature & Seal of Professional Surveyor 320 |Acres Certificate No 7254 John S. Piper 1 1320 1650 1980 2310 2640 500 1500 330 Dee 088 2000 1000

 \bigcirc = Staked Location • = Producing Well \checkmark = Injection Well \diamond = Water Supply Well \rightarrow = Plugged & Abandon Well \bigcirc = Found Section Corner, 2 or 3" Iron Pipe & GLO B.C. \bigcirc = Found /4 Section Corner, 1" Iron Pipe & GLO B.C.

ADDITIONAL INFORMATION ON THE LOCATION

State Plane Coordin	otes		
Northing 718628.54 (1927= 718563.25)		Easting 711870.812 (1927= 670692.96)	
Latitude 32°58'27.40"		Longitude 103°46'38.09"	
Zone	North American Datum	Combined Grid Factor	Coordinate File
זאר	1983	0.99994239	Texmack6.cr5
ing File		Field Book	
-Chaves_36		Chaves County #1, Pg. 4	



Received to the contract of th